

(붙임 1)

사 진 자 료



<봉분 전경(현재 상태)>



<연도 천장석 균열>



<연도 천장석 하부 긴급보강(임시 지주목 설치)>



<현실 내부벽 배부름(측면)>